OPTIONAL ACCESSORIES



GMK 38

Measuring cable, BNC to 2x banana plugs



GHE 91 *

Item No. 601263 Reciprocating Piston Electrode



GSE 91*

Item No. 601266

Impact electrode, for driving in \emptyset 2.5 mm steel poles



Handle, suitable for GSE91



Item No. 601270 Impact electrode with handle, for driving in Ø 2.5 mm steel poles or for GMS 300/91



Steel pins 9 steel poles (3 each, 12, 16 and 23 mm long) in plastic box, Ø 2.5 mm



GST 91/40

Item No 601275 Steel pins 10 steel poles, 40 mm long, Ø 2.5 mm, in a plastic box



Steel pins 2 pieces of teflon-insulated steel poles, 45 mm long, Ø 2.5 mm

GST 60i

Item No. 601279 Steel pins, ditto, 60 mm long





GOK 91

Item No. 601287 Surface measuring caps (pair, for screwing onto GSG 91/GSE 91)



GMS 300/91

Measuring rods (pair, for screwing onto GSG 91/GSE 91), for wood chips, wood wool, paper, cardboard, etc.



Item No. 601281

2 steel pins with hole, 15 mm long, \emptyset 3.8 mm (for direct connection of the GMK 38 measuring cable)



Steel poles, ditto, Ø 3.8 x 25 mm





GBSK 91 *

Item No. 601293

Wire brush probe for material moisture measurement



Item No. 601294

Wire brush probe for material moisture measurement



Flat electrode for material moisture measurement, for screed,



Item No. 601299

Conductive paste for materialmoisture measurement, for surface measurement and depth measurement in walls, screed etc. with brush probes



GSF 50K (43 cm)

Material moisture insertion probe, (without temperature sensor) for measurements at measuring depths of up to 40 cm or 107 cm, incl. 1 m connection cable.

Suitable for: wood chips, wood wool, wood shavings, straw, hay, grain, sawdust, etc.



GSF 50TFK (43 cm)

Material moisture insertion probe, with temperature sensor for measurement at measuring depths of up to 40 cm or 107 cm, incl. 1 m connection cable

Suitable for: wood chips, wood wool, wood shavings, straw, hay, grain, sawdust, etc.



Item No. 601316

Material moisture insertion probe, (without temperature sensor) for measurement in pressed bales at a depth of 60 cm, incl. 1 m connection cable.

Suitable for: pressed hay and straw bales, grain

^{*} Measuring cable GMK 38 required for GHE 91, GSE 91, GSG 91, GST 15B/25B/40B, GBSK 91, GBSL 91, GEF 38, GSP 91, GMZ 38